

(Your Logo)

Complimentary Vehicle Inspection
02/10/15 9:00 AM




Nissan 2012 Altima Sedan 215/55R17



Stopping Check **FAILED**

- Front-to-Rear Brake Balance
- Front Axle Left-to-Right
- Rear Axle Left-to-Right



Recommend a Brake Inspection for Thickness Verification


Tire Tread Depth **PASSED**



Tread depth values are in inches.

Wheel Alignment **FAILED**

- Front Total Toe
- Front Camber
- Rear Camber
- Rear Total Toe



Recommend an All Wheel Alignment for Added Tire Life, Fuel Economy and Safety

Diagnostic Check **PASSED**

- Check Engine Light - OFF
- 0 Trouble Codes are present




No Additional Service Needed

Battery Health **PASSED**



State of Health



- Measured: 461 CCA Voltage: 12.12 V
- OEM Ref.: 585 CCA

Good Battery

SAMPLE

(Your Logo)

Complimentary Vehicle Inspection
02/10/15 9:00 AM





Nissan 2012 Altima Sedan 215/55R17



Last in Date: 10/29/14 3:17:45 PM

Tire Tread Depth **FAILED**



Tread depth values are in inches.



*For details see www.hunter.com/stopping

SAMPLE


Quick Check™ — Configurations for Every Shop




Clear Floor Configurations



Surface & Flush Brake Plate Configurations





Quick Tread™ Configurations



Drive-Thru Sensors



Drive-Under Sensors



Embedded Console

0215AH

Copyright © 2015, Hunter Engineering Company

Form 6965-T, 02/15

