

Vehicle Systems Report

08/15/2022 4:19 PM CDT
Repair order 76251
Technician ID Ryan
Customer Name Hunter

Year: 2014
Make: GMC
Model: Sierra 1500
Submodel: SLT
Engine: 6.2
VIN: 3GTU2VEJ8EG537096
Odometer 143943

Scantool: Hunter
Software Version 5.0.1.1
Serial #: 00DVMN5021021558HU

Diagnostics software featuring officially licensed OEM data from ETI



Hunter Engineering
11250 Hunter Dr.
Bridgeton MO 63044

Diagnostic Health Report		
	Pre-Scan 08/12/2022 10:48 AM CDT	Post-Scan 08/12/2022 11:27 AM CDT
Modules Scanned:	25	25
Diagnostic Trouble Codes:	2	0
System		
SEAT MEMORY CTRL DRIVER	2	OK
B172E-01	HISTORY CODES	OK
B172E-02	HISTORY CODES	OK
AIRBAG	OK	OK
AMPLIFIER	OK	OK
BODY CONTROL (TPMS)	OK	OK
CLIMATE (HVAC)	OK	OK
ELECTRONIC BRAKE CONTROL	OK	OK
ENGINE	OK	OK
FRONTVIEW CAMERA MODULE <small>ADAS</small>	OK	OK
HUMAN MACHINE INTERFACE MODULE	OK	OK
HVAC CONTROLS	OK	OK
INSTRUMENT PANEL	OK	OK
PARKING ASSIST CONTROL MODULE <small>ADAS</small>	OK	OK
PASSENGER PRESENCE MODULE	OK	OK
POWER STEERING CONTROL	OK	OK
RADIO	OK	OK

RADIO CONTROLS	OK	OK
STEERING WHEEL ANGLE SEN MODULE	OK	OK
TELEMATICS COMM INTERFACE	OK	OK
TRANSFER CASE	OK	OK
TRANSMISSION	OK	OK
CHASSIS CONTROL MODULE	NOT FOUND	NOT FOUND
HYBRID PCM	NOT FOUND	NOT FOUND
LEFT SIDE OBJ DET MODULE ADAS	NOT FOUND	NOT FOUND
MEDIA DISK PLAYER	NOT FOUND	NOT FOUND
PARKING BRAKE CONTROL MOD	NOT FOUND	NOT FOUND

ADAS Calibration

Front Facing Camera **COMPLETE**
Vehicle Direction Camera Learn 08/12/2022 10:59 AM CDT

Cameras are used to monitor vehicle surroundings for Advanced Driver Assistance Systems (ADAS). These systems assist the driver using warnings, braking, or steering actions to maintain lane position or to mitigate collision risk. Calibration helps to ensure the system performs properly.

Special Tests

Steering Wheel Angle Sensor Learn (SAS) **COMPLETE**
08/12/2022 10:53 AM CDT

Signature of Approval

Customer Signature _____ Date _____